# Carderock Division Naval Surface Warfare Center


Bethesda, Md. 20084-5000

CARDIVNSWC-SSM-64-94/18 March 1995

Survivability, Structures, and Materials Directorate Technical Report

### A Post-Cure Study of Glass/Vinyl Ester Laminates Fabricated by Vacuum Assisted Resin Transfer Molding

by Thomas Juska Steve Mayes



19950911 121

DIES QUALITY INSPECTED 5



Approved for public release; distribution unlimited.

### CONTENTS

		Page
ADM INT EVA FLI THE DIS SUM REE	STRACT MINISTRATIVE INFORMATION PRODUCTION ALUATION PROCEDURE EXURAL STRENGTH RESULTS ERMAL ANALYSIS RESULTS SCUSSION MMARY FERENCES PENDIX	1 1 2 2 4 4 5 5
	TABLES	
1.	Flexural strength as a function of post-cure conditions.	. 3
	FIGURES	
1.	Flexural Strength of WR/510A as a function of post-cure conditions	. 3
2.	Modulus-temperature behavior of WR/510A 24 hours after fabrication	. 6
3.	Modulus-temperature behavior of WR/510A 1 week after fabrication	. 7
4.	Modulus-temperature behavior of WR/510A 1 month after fabrication	. 8
5.	Modulus-temperature behavior of WR/510A 3 months after fabrication	. 9
6.	Modulus-temperature behavior of WR/510A 1 year after fabrication	. 10
7.	Modulus-temperature behavior of WR/510A after a 140 F post-cure	. 11
8.	Modulus-temperature behavior of WR/510A after a 160 F post-cure	. 12
9.	Modulus-temperature behavior of WR/510A after a 180 F post-cure	. 13
10.	. Modulus-temperature behavior of WR/510A after a 200 F post-cure	. 14
11.	. Tg of WR/510 A as a function of post-cure conditions	. 15
12.	. Tg as function of percent cure for Derakane 411 (from reference 2)	. 15

#### ABSTRACT

A post-cure study was made of a vinyl ester laminate fabricated by vacuum assisted resin transfer molding. One day after fabrication the glass transition temperature (Tg) was about 154 F and the flexural strength was 52 ksi, which are low values. With time at room temperature, however, both strength and Tg increased to acceptable levels. Room temperature postcuring increased the Tg to about 200 F and the flexural strength to 78 ksi. In addition it was found that the resin cures very rapidly at elevated temperature, which allows the resin Tq to remain above the temperature of the environment for most heating rates. increases in strength and Tg due to post-curing reactions at ambient temperature and the rapid increase in Tg with the temperature of the environment, we concluded that post-curing of structures fabricated by VARTM is not necessary.

#### ADMINISTRATIVE INFORMATION

The work described herein was conducted under the Organic Composites Ship Structures Project (RH21S12) as part of a Congressional Special Interest Initiative, Navy Program Element 0621221N. The project was sponsored and managed by the Office of Naval Research, ONR 334, and executed by the Carderock Division, Naval Surface Warfare Center under work unit 1-6600-042-40.

#### INTRODUCTION

Laminating resins used in marine construction are as a rule not fully cured. Although these materials are called "room temperature curing" or "cold curing" resins, the reaction exotherm increases the temperature well above ambient, which advances the cure state. Information on the role of resin exotherm on the degree of cure is not available. The purpose of this study was to determine if composite structures for Naval applications should be post-cured, particularly those made by vacuum assisted resin transfer molding (VARTM), which are characterized by low resin contents and therefore low exotherm temperatures.

The degree of cure cannot be directly measured, but it can be indirectly assessed using differential scanning calorimetry (DSC). During a DSC scan, any initially uncured component cures during the test, and the DSC detects the heat of reaction of this uncured component. To determine the percent cure of a given sample, the heat of reaction (per unit weight) of the specimen is assumed to be proportional to the fraction of uncured resin. That is, the percent cure of a specimen =  $(1-\Delta H_X/\Delta H_C)$  X 100, where  $\Delta H_X$  is the heat of reaction of the specimen and  $\Delta H_C$  is the heat of reaction measured during full cure. This method works well for neat resin samples, but its usefulness for laminates depends on the accuracy of measuring the resin content of each specimen tested. This is difficult given that a DSC uses roughly

10 mg samples.

The degree of cure is related to the crosslink density. There is a maximum possible crosslink density that a given thermoset resin could achieve given enough time at temperature, and as mentioned, the typical resin in marine laminates operates at less than 100 percent reacted (1). There are many resin properties which depend on the crosslink density, so there are many indirect methods which can be used to assess the degree of cure once the methods are calibrated with data established by DSC measurements.

In a study at Dow Chemical Co. (2), Barcol hardness, acetone weight gain, residual styrene content, heat distortion temperature (HDT), and glass transition temperature measured with Dynamic Mechanical Analysis (DMA) were all compared with DSC data. All five methods were acceptable alternatives to DSC, with the exception of Barcol hardness, which was insensitive to degree of cure above 85%. The Dow study reported that the glass transition temperature (Tg) of the vinyl ester evaluated (Derakane 411-45) increased substantially with degree of cure. The data show that neat resin castings were 73.5% cured after 1 day at room temperature and had a Tg of only 112°F. Tg was a essentially proportional to the degree of cure, eventually reaching about 225°F at 100% cure.

In our study, flexural strength and glass transition temperature were used to characterize the VARTM laminate. The laminate was composed of 6 plys of 24 oz woven roving (OC24P-107B) and a brominated vinyl ester (Dow Derakane 510A). It was cured with 1.25% MEKP and 0.3% CoNap. The weight percent glass was measured at 71.3 and the void content was negligible.

#### EVALUATION PROCEDURE

The flexural strength and DMA scans of a laminate made by VARTM were measured as a function of time at room temperature, and also after various post-cure conditions.

The flexural testing was done in the warp direction using ASTM D790 (3-point bend) at a span-to-depth ratio of about 32:1. The thermal analysis was done using a Polymer Labs MK II DMTA (Dynamic Mechanical Thermal Analysis) in the single cantilever beam mode at 10 Hz. The data was taken at heating rates of 5 F/min (3 C/min) and 18 F/min (10 C/min).

#### FLEXURAL STRENGTH RESULTS

The flexural strength as a function of post-cure conditions is given in Table 1, and plotted in Figure 1. The raw data is provided in the Appendix. It is clear from inspection of the flexural strength data that the resin continued to cure slowly for many months while held at ambient temperature. This room temperature post-cure allowed the laminate to develop a flexural strength comparable to that attained with at 140 F post-cure.

It appears from this data that an optimum post-cure temperature exists, which for this resin is about 160 F. The post-cures at 180 F and 200 F resulted in a 20% decrease in strength. Since these temperatures are well below those required for resin degradation, the most likely cause for the strength

loss is a decrease in resin failure strain to below the 4% minimum value required for full laminate mechanical property development (3).

Table 1. Flexural strength as a function of post-cure conditions.




Figure 1. Flexural strength of WR/510A as a function of post-cure conditions.

#### THERMAL ANALYSIS RESULTS

The DMA scans taken in this study are given in Figures 2-10. Figure 2 shows the modulus (log E') as a function of laminate temperature after 24 hours at room temperature, Figure 3 after 1 week, Figure 4 after 1 month, Figure 5 after 3 months, and Figure 6 after 1 year. Figure 7 is the modulus-temperature plot for the sample post-cured at 140 °F, Figure 8 is the behavior after a 160 °F post-cure, Figure 9 after 180 °F, and Figure 10 after a 200 °F post-cure.

Figures 2-5 were taken at a heating rate of 5 °F/min (3 °C/min). We learned in this study that this heating rate is too slow. It gives the material enough time at temperature to post-cure during the test, and the DMTA then measures the Tg of the post-cured material. Although it appears from the data that the resin Tg is 250 °F (120 °C) in Figures 2-5, this is the post-cured value.

Inspection of Figures 2-5 show a transition, indicated by a drop in modulus, at temperatures well below 250 °F. For example, in Figure 2 the transition starts about 154 °F (68 °C). We believe that this transition is the actual Tg of the material.

Figures 6-10 show the DMA data measured with a heating rate of 18 °F/min (10 °C/min). Interpretation of the data is straightforward because the material cannot cure fast enough at this rate to keep its Tg above the test temperature. The value of Tg is taken at the knee in the modulus-temperature plots. The knee is located by the intersection of lines extrapolated from linear portions of the curve, as shown on each plot.

We have determined the value of Tg from the DMA plots and plotted these values in Figure 11. For comparison we show the DMA data taken in the Dow study in Figure 12.

The most significant discovery is that the Tg increases almost 50 °F after a year at room temperature. As mentioned, flexural strength also increases with room temperature post-curing. The data in Figure 11 supports and provides an explanation for the mechanical property data.

It is interesting to compare the data taken by Dow on Derakane 411 with that generated in this study on Derakane 510A. In both cases, the difference between newly fabricated Tg and maximum Tg was about 100 °F. Also, the initial increase in the degree of cure did not improve the Tg in either study.

#### DISCUSSION

The data taken in this study indicate that post-cure requirements should not, in general, be imposed upon laminates for use in Naval structures, including those made with VARTM. Three facts have allowed us to make this statement: 1) the laminate strength increases to an acceptable value with time at ambient conditions, 2) the resin Tg increases to an acceptable value with time at ambient conditions, and 3) the resin Tg increases rapidly with the temperature of the environment.

The main concern with the cure state of resins is the low Tg associated with low crosslink densities. Although the cure state can advance rapidly at elevated temperature, failure could result

from a temperature rise too rapid for the material to respond. Our data indicates that this rate of temperature increase is between about 5 °F/min and 20 °F/min for Derakane 510A, that is, at rates below 5 °F/min the post-curing reactions will keep the Tg above the temperature of the environment, but heating rates higher than 20 °F/min could allow the temperature to exceed Tg. We feel that post-cure requirements should be imposed only if rapid rates of temperature increase are expected.

#### SUMMARY

A vinyl ester laminate fabricated by VARTM was evaluated to determine if these low resin content materials should be post-cured due to a reduction in resin exotherm. Given the results listed below, we concluded that post-curing is not necessary unless a rapid temperature increase is expected soon after fabrication.

- 1. The mechanical and thermal properties of the laminate were initially relatively low due to low percent cure.
- 2. Room temperature post-cure increased the flexural strength from its initial value of 52 ksi to 78 ksi after 6 months in ambient conditions, a value comparable to that attained with a 140 °F post-cure.
- 3. Room temperature post-cure increased the Tg from its initial value of 154 °F to about 200 °F after a year in ambient conditions.
- 4. The degree of cure increased rapidly with temperature. When heated at 5 °F/min the resin Tg remained above the temperature of the environment. However, when heated at 18 °F/min the temperature exceeded Tg.
- 5. The optimum post-cure temperature for Derakane 510A is 160 °F. Higher temperature post-cures result in a loss in strength, probably due to a reduction in resin failure strain.

#### REFERENCES

- 1. T. Juska and J.S. Mayes, "The Properties of Marine Laminates Made by Hand Lay-up", in preparation.
- 2. P. Puckett, Reaction Molding & Composites Applications Development Lab, Dow Chemical Co., unpublished data.
- 3. T. Juska, J.S. Mayes, and M.J. Russell, "Evaluation of Marine Construction Materials and Fabrication Methods", Proceedings of MACM-5, Composites Education Association, Inc., Melbourne, FL, April 18-20, 1994.

## WR/510A - 24 hours RT 3 degC/min 11.0 10.5 10.0 . Бод 9.5 9.0 8.5 8.0 100 50 150 200 Temperature (degC)

Figure 2. Modulus-temperature behavior of WR/510A 24 hours after fabrication.

### WR/510A - 1 week RT 3 degC/min




Figure 3. Modulus-temperature behavior of WR/510A 1 week after fabrication.

## 

Temperature (degC)

WR/510A - 1 month RT

Figure 4. Modulus-temperature behavior of WR/510A 1 month after fabrication.

## WR/510A - 3 months RT 3 degC/min




Figure 5. Modulus-temperature behavior of WR/510A 3 months after fabrication.




Figure 6. Modulus-temperature behavior of WR/510A 1 year after fabrication.

#### 11.0 10.5 10.0

WR/510A - 140F Post Cured

Figure 7. Modulus-temperature behavior of WR/510A after a 140 F post-cure.

#### 11.0 10.5 10.0

WR/510A - 160F Post Cured

Figure 8. Modulus-temperature behavior of WR/510A after a 160 F post-cure.

Temperature (degC)

## 10 degC/min 11.0 10.5 10.0 Ш **6**9.5 9.0 8.5 8.0 50 100 150 200 0 Temperature (degC)

WR/510A - 180F Post Cured

Figure 9. Modulus-temperature behavior of WR/510A after a 180 F post-cure.

# WR/510A - 200F Post Cured 10 degC/min




Figure 10. Modulus-temperature behavior of WR/510A after a 200 F post-cure.




Figure 11. Tg of WR/510 A as a function of post-cure conditions.




Figure 12. Tg as function of percent cure for Derakane 411 (data taken from reference 2).

APPENDIX. Raw Flexural Strength Data

Post-cure Temp; Time	thickness (inches)	width (inches)	load (lbs)	strength (ksi)
Ambient; 24 hours  MEAN STD DEV	.138 .135 .140 .138 .140	.505 .504 .507 .505 .503	72 80 73 72 75	50.5 58.8 49.6 50.5 51.3 52.1
Ambient; 1 week  MEAN STD DEV	.134 .135 .136 .141	.503 .503 .507 .508	83 82 97 90	62.0 60.4 69.8 63.1 63.8
Ambient; 1 month  MEAN STD DEV	.141 .136 .138 .136	.504 .499 .502 .503	102 92 109 103	4.1 68.7 65.0 83.9 74.7 73.1 8.2
Ambient; 3 months  MEAN STD DEV	.136 .140 .135 .139	.502 .503 .503 .504	108 105 84 99	78.5 71.9 61.9 68.6 70.2 6.9
Ambient; 6 months  MEAN STD DEV	.135 .144 .135 .132	.503 .507 .502 .505	122 85 107 115	89.8 54.5 78.9 88.2 77.8 16.3
140 °F; 8 hours	.138 .134 .139	.501 .501	113 102 114	79.9 76.5 79.5
MEAN STD DEV	.139	.503	112	77.8 78.4 1.6
160 °F; 4 hours	.138 .138 .140 .135	.505 .503 .504 .505	135 131 120 123	94.7 92.3 82.0 90.2
MEAN STD DEV				89.8 5.5

APPENDIX. Raw Flexural Strength Data, Cont.

Post-cure	Temp;Time	thickness (inches)	width (inches)	load (lbs)	strength (ksi)
180 °F; 4	hours	.135 .134 .134 .139	.504 .502 .500	91 99 90 100	66.9 74.1 67.7 69.6
MEAN STD DEV					69.6 3.2
200 °F; 4	hours	.140 .135 .137	.498 .505 .500 .499	109 89 106 104	75.3 65.3 76.2 71.8
MEAN STD DEV					72.1 4.9

### INITIAL DISTRIBUTION

Copies	CENTER DISTRIBUTION				
4 DTIC	Copies Code Name				
5 ONR 1 332 (Kelly) 1 332 (Fishman) 1 332 (Sloter 1 334 (Gagorik) 1 334 (Rajapakse)	1 0115 Caplan 1 601 Morton 1 644 Castelli 1 65 Beach 1 65X Benson 1 655 Critchfield 1 6551 Phyillaier				
6 NAVSEA 1 05Pl3 (Kadala) 1 05Pl3 (Kurzweil) 1 03P (Packard) 1 PMS30041 (Sheedlo) 1 PMS30041 (McGrath) 1 PMS3003 (Hollingsworth	5 6551 Mayes 1 6551 Nguyen 1 6552 Potter 1 6552 Loup 1 6552 Gipple 1 6553 Crane				
<pre>NAVAIR 1 5304 C2 (Moore) 1 5304 C2 (Thompson)</pre>	1 6553 Williams				
1 NRL 1 6383 (Gause)					
1 Carderock Division, NSW 1 60 (Augl)	C White Oak				
Carderock Division, NSWC Combatant Craft Detachment 1 231 (Russell) 1 2302 (Rowland)					
1 Dahlgren Division, NSWC Coastal Systems Station 1 2310 (Wyman)					
1 NUWC 1 8215 (Tucker)					
1 NAWC 1 6064 (Cochran)					
<pre>1 U.S. Coast Guard HDQTRS 1 G-ENE-5A (Shepard)</pre>					
1 Norfolk Naval Shipyard 1 964P (Hatton)					

H. Benson Dexter
Langley Research Center
Mechanics of Materials Branch
Mail Stop 226
Hampton, VA 23665-5225

Mr. Bill Seemann Seemann Composites, Inc. P.O. Box 3449 Gulfport, MS 39505

Dr. Walter Bradley
Dept of Mechanical Engineering
Texas A&M University
College Station, TX 77843-3123

Mr. Longin Greszczuk McDonnell Space Systems Company 5301 Bolsa Avenue Huntington Beach, CA 92647

Mr. Steve Kopf EI DuPont DeNemours & Co. Composites Division Chestnut Run Plaza Box 80702 Wilmington DE 19880-0702

Dr. Don Adams
Mechanical Engineering Dept.
Univ. of Wyoming
Laramie, WY 82071

Dr. Travis Bogetti Mechanics and Structures Branch U.S. BRL Aberdeen, MD 21005-5066

Dr. Jack Gillespie Center for Composite Materials Composites Manufacturing Lab. University of Delaware Newark, DE 19716

Dr. Mac Puckett
Dow Chemical Company
Reaction Molding & Composites
Applications Development Lab
Building B-2009
Freeport, Texas 77541

Mr. Malcolm Willis Swiftships, Inc. P.O Box 1908 Morgan City, LA 70381 Dr. Don Hunston Polmer Composites Group NIST Bldg. 224, Rm. A209 Gaithersburg, MD 20899

Mr. Tony Falcone Boeing Aerospace Company P.O. Box 3999, MS 73-09 Seattle, WA 98124-2499

Mr. Brian Eccles Intermarine USA P.O. Box 3045 Savannah, GA 31402-3045

Mr. Hal Coleman Advanced Composites Group, Inc. 515 Barton Circle Strafford, PA 19087-5415

Mr. Bill Haskell III
Army Materials and Mechanics
Research Center
Composites Development Division
Watertown, MA 02172

Mr. Eric Greene Structural Composites, Inc. 18 Cushing Avenue Annapolis, MD 21403

Ms. Patricia Helbling Composites Education Assn., Inc. P.O. Box 130 Melbourne, FL 32902

Dr. Jim Seferis
Dept. of Chemical Eng., BF-10
University of Washington
Seattle, WA 98195

Mr. George Tunis Hardcore Composites 19 Lukens Drive New Castle, DE 19720

Mr. Paul Biermann Johns Hopkins University Applied Physics Laboratory Johns Hopkins Road Laurel, MD 20707 Mr. Terry McCabe Interplastics Corporation Commercial Resins Division 1225 Wolters Blvd. Vadnals Heights, MN 55110-5145

Mr. Robert Schofield Naval Architect N 1742 Shore Drive Marinette, WI 54143

Mr. Mark Livesay Sunrez Corporation 374 Merritt Drive El Cajon, CA 92020

Mr. Jeff Davidson Newport News Shipbuilding Bldg 600-1, Dept. E-20 4101 Washington Ave. Newport News, VA 23607

Mr. Will Warren
Ingalls Shipbuilding
P.O. Box 149
Pascagoula, MS 39568-0149

Mr. Bruce Pfund
Bruce Pfund Special Projects
RR#3, Box 419-C Shore Road
#7 Windover Turn
Westerly, R.I. 02891

Mr. Eric Goetz Goetz Custom Sailboats 15 Broad Common Road Bristol, R.I. 02809

Mr. Val Jenkins Cigarette Racing Team 3131 N.E. 188th Street North Miami Beach, FL 33180

Mr. Everett Pearson TPI, Inc. P.O. Box 328 Warron, R.I. 02885

Mr. Steve Crane
US Marine
P.O. Box 9029
Everett, WA 98206

Dr. Gail Brinkman
Director, Composites Laboratory
National Institute for Aviation
Research
The Wichita State University
Wichita, KS 67260-0093

Mr. Rick Rust Westport Shipyard, Inc. P.O. Box 308 Westport, WA 98595

Mr. Khiem Nguyen Christensen Motor Yacht Company 4400 East Columbia Way Vancouver, WA 98661

Mr. Peter Wilson Marine Construction Management P.O. Box 1289 Newport, R.I. 02840

Mr. Philip Beirnes North Coast Boats, Inc. 401 Alexander Ave. #407 Tacoma, WA 98421

Dr. John Kunz Mega Marine Structures, Inc. 3200 W. 71st Ave., #14 Westminster, CO 80030

Mr. Paul Lazarus Professional Boatbuilder Magazine RR1, Box 683 Wiscasset, ME 04578

Mr. Robert Scott
Gibbs & Cox, Inc.
1235 Jefferson Davis Highway
Crystal Gateway 1, Suite 700
Arlington, VA 22202

LT Zan E. Miller, USN RESUPSHIP Savannah P.O. Box 1208 Savannah, GA 31402-1208

Dr. Carol Schutte NIST Bldg 224, Rm A209 Gaithersburg, MD 20899